

03500.010106.5



Clofe
EFW
S
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

TOSHIKAZU OHNISHI ET AL.

Appln. No.: 10/615,995

Filed: July 10, 2003

For: ELECTRON-EMITTING DEVICE,
ELECTRON SOURCE, AND
IMAGE-FORMING APPARATUS

U.S. Patent No.: 6,908,356 B2

Issued: June 21, 2005

)
:
)
:
)
:
)
:
)
:
)
:
)
:
)
:
)

Examiner: J.L. Williams
Group Art Unit: 2879
August 18, 2006

Certificate
AUG 23 2006
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Attest: [Signature] Attest: [Signature]

Attest: [Signature]

Attest: [Signature]


Attest: [Signature]

Attest: [Signature]

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Frank A. DeLucia
Attorney for Patentees
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 541638v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

United States Patent Documents,

“5,006,883 A 4/1991 Ohashi et. al ... 313/309” should read
--5,006,883 A 11/1991 Yoshioka et al ... 313/309--; and

Other Publications, after “ “Influence of Organic Molecules ...”:

“Characterisitc” should read --Characteristic--;
after “H. Hartwell, et al.”: “Meeting (1976)” should read --Meeting
(1975)--; and
after “ “Carbon-Nanoslit Model”: “m. Bischoff,” should read --M.
Bischoff,--.

ON THE TITLE PAGE [75]:

Inventors, “Toshikazu Ohnishi, Tokyo (JP); Masato Yamanobe, Tokyo (JP); Ichiro Nomura, Kanagawa-ken (JP); Hidetoshi Suzuki, Kanagawa-ken (JP);Yoshikazu Banno, Kanagawa-ken (JP); Takeo Ono, Tokyo (JP); Masanori Mitome, Kanagawa-ken (JP)” should read --Toshikazu Ohnishi, Machida (JP); Masato Yamanobe, Machida (JP); Ichiro Nomura, Atsugi (JP); Hidetoshi Suzuki, Fujisawa (JP);Yoshikazu Banno, Ebina (JP); Takeo Ono, Machida (JP); Masanori Mitome, Yokohama (JP)--.

COLUMN 1:

Line 22, “devices;” should read --devices--;
Line 28, “Emission”.” should read --Emission”,--; and
Line 43, “In₂O₃/SnO₂” should read --In₂O₃/SnO₂--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 27, "there" should read --there is--.

COLUMN 5:

Line 22, "incorporation" should read --incorporating--.

COLUMN 6:

Line 42, "hun-" should be deleted;

Line 43, "dreds of several" should read --several hundred--; and

Line 51, "hundreds of several" should read --several hundred--.

COLUMN 9:

Line 6, "is applied" should be deleted; and

Line 63, "greater" should read --greater than--.

COLUMN 10:

Line 5, "needs" should read --need--;

Line 35, "to" should read --to as--; and

Line 46, "will" (first occurrence) should read --will be--.

COLUMN 11:

Line 15, "are" should read --are more--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13:

Line 9, "to" should read --to as--;
Line 22, "wiring" should read --wirings--; and
Line 41, "ealized" should read --realized--.

COLUMN 14:

Line 64, "denotes" should read --denote--.

COLUMN 17:

Line 7, "of" should be deleted.

COLUMN 18:

Line 29, "throughput" should read --throughout--;
Line 40, "provides" should read --provide--; and
Line 55, "to" should read --to as--.

COLUMN 19:

Line 23, "fro" should read --from--; and
Line 45, "denotes" should read --denote--.

COLUMN 21:


Line 14, "denotes" should read --denote--; and
Line 51, "milliseconds" (first occurrence) should read --millesecond--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 18, "16.6 msec." should read --16.6 msec.,--.

COLUMN 25:

Line 25, "source" should read --sources--.

COLUMN 27:

Line 13, "1x110 torr" should read --1x10⁻⁴ torr--; and

Line 26, "1x10' torr." should read --1x10⁻⁶ torr.--.

COLUMN 28:

Line 37, "signals 11 through 1200" should read --signals I1 thorugh I200--;

Line 41, "1005 a" should read --1005 sends a--; and

Line 43, "signals 11 through 11200" should read --signals I1 through I200--.

COLUMN 29:

Line 14, "display" should read --displaying--;

Line 23, "synchornism" should read --synchronism--; and

Line 48, "bad" should read --had--.

COLUMN 30:


Line 1, "was" should read --were--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 31:

Line 45, "ing" should read --ing to--; and
Line 65, "graphic" should read --graphics--.

COLUMN 32:

Line 2, "participate" should read --participate--; and
Line 3, "other" should read --in other--.

COLUMN 33:

Line 16, "participate" should read --participate in--; and
Line 47, "device" should read --devices--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

United States Patent Documents,

“5,006,883 A 4/1991 Ohashi et. al ... 313/309” should read

--5,006,883 A 11/1991 Yoshioka et al ... 313/309--; and

Other Publications, after ““Influence of Organic Molecules ...”:

“Characterisitc” should read --Characteristic--;

after “H. Hartwell, et al.”: “Meeting (1976)” should read --Meeting (1975)--; and

after ““Carbon-Nanoslit Model”: “m. Bischoff,” should read --M. Bischoff--.

ON THE TITLE PAGE [75]:

Inventors, “Toshikazu Ohnishi, Tokyo (JP); Masato Yamanobe, Tokyo (JP); Ichiro Nomura, Kanagawa-ken (JP); Hidetoshi Suzuki, Kanagawa-ken (JP);Yoshikazu Banno, Kanagawa-ken (JP); Takeo Ono, Tokyo (JP); Masanori Mitome, Kanagawa-ken (JP)” should read --Toshikazu Ohnishi, Machida (JP); Masato Yamanobe, Machida (JP); Ichiro Nomura, Atsugi (JP); Hidetoshi Suzuki, Fujisawa (JP);Yoshikazu Banno, Ebina (JP); Takeo Ono, Machida (JP); Masanori Mitome, Yokohama (JP)--.

COLUMN 1:

Line 22, “devices;” should read --devices:--;

Line 28, “Emission”. should read --Emission”,--; and

Line 43, “In₂O₃/SnO₂” should read --In₂O₃/SnO₂--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 27, "there" should read --there is--.

COLUMN 5:

Line 22, "incorporation" should read --incorporating--.

COLUMN 6:

Line 42, "hun-" should be deleted;

Line 43, "dreds of several" should read --several hundred--; and

Line 51, "hundreds of several" should read --several hundred--.

COLUMN 9:

Line 6, "is applied" should be deleted; and

Line 63, "greater" should read --greater than--.

COLUMN 10:

Line 5, "needs" should read --need--;

Line 35, "to" should read --to as--; and

Line 46, "will" (first occurrence) should read --will be--.

COLUMN 11:

Line 15, "are" should read --are more--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13:

Line 9, "to" should read --to as--;
Line 22, "wiring" should read --wirings--; and
Line 41, "ealized" should read --realized--.

COLUMN 14:

Line 64, "denotes" should read --denote--.

COLUMN 17:

Line 7, "of" should be deleted.

COLUMN 18:

Line 29, "throughput" should read --throughout--;
Line 40, "provides" should read --provide--; and
Line 55, "to" should read --to as--.

COLUMN 19:

Line 23, "fro" should read --from--; and
Line 45, "denotes" should read --denote--.

COLUMN 21:

Line 14, "denotes" should read --denote--; and
Line 51, "milliseconds" (first occurrence) should read --millesecond--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only

PRINTER'S TRIM LINE

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 18, "16.6 msec." should read --16.6 msec.,--.

COLUMN 25:

Line 25, "source" should read --sources--.

COLUMN 27:

Line 13, "1x110 torr" should read --1x10⁴ torr--; and

Line 26, "1x10' torr." should read --1x10⁻⁶ torr.--.

COLUMN 28:

Line 37, "signals 11 through 1200" should read --signals I1 thorugh I200--;

Line 41, "1005 a" should read --1005 sends a--; and

Line 43, "signals 11 through 11200" should read --signals I1 through I200--.

COLUMN 29:

Line 14, "display" should read --displaying--;

Line 23, "synchornism" should read --synchronism--; and

Line 48, "bad" should read --had--.

COLUMN 30:

Line 1, "was" should read --were--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,356 B2

DATED : June 21, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 31:

Line 45, "ing" should read --ing to--; and
Line 65, "graphic" should read --graphics--.

COLUMN 32:

Line 2, "participate" should read --participate--; and
Line 3, "other" should read --in other--.

COLUMN 33:

Line 16, "participate" should read --participate in--; and
Line 47, "device" should read --devices--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,356 B2

No. of add'l. copies
@ 30¢ per page

